

School Name	Test Date (dd-mm-yyy)	Sample Type	Fixture Type	Fixture Location Description	Lead Result (mg/L)	Exceeds Maximum Acceptable Concentration	Mitigation ID	Mitigation Description
Wickaninnish Community School	24-04-2024	First Draw	DW	Corridor 140	0.0003	No	NA	FALSE
Wickaninnish Community School	24-04-2024	Flushed	DW	Corridor 140	0.0003	No	NA	FALSE
Wickaninnish Community School	24-04-2024	First Draw	DW	Corridor 141	0.0051	Yes	2A	Post signage near the fixture to run the water at least one minute before drinking or using water for food preparation until replacement. Retest fixture following replacement.
Wickaninnish Community School	24-04-2024	Flushed	DW	Corridor 141	0.0003	No	2A	Post signage near the fixture to run the water at least one minute before drinking or using water for food preparation until replacement. Retest fixture following replacement.
Wickaninnish Community School	24-04-2024	First Draw	CF	Resource Room 104	0.0026	No	NA	FALSE
Wickaninnish Community School	24-04-2024	Flushed	CF	Resource Room 104	0.0049	No	NA	FALSE
Wickaninnish Community School	24-04-2024	First Draw	DW	Corridor 142	0.0003	No	NA	FALSE
Wickaninnish Community School	24-04-2024	Flushed	DW	Corridor 142	0.0003	No	NA	FALSE
Wickaninnish Community School	24-04-2024	First Draw	BF	Staff Washroom 135	0.0298	Yes	2A	Post signage near the fixture to run the water at least one minute before drinking or using water for food preparation until replacement. Retest fixture following replacement.
Wickaninnish Community School	24-04-2024	Flushed	BF	Staff Washroom 135	0.003	No	2A	Post signage near the fixture to run the water at least one minute before drinking or using water for food preparation until replacement. Retest fixture following replacement.
Wickaninnish Community School	24-04-2024	First Draw	CF	Classroom 107	0.0081	Yes	4F	Install a NSF 53/42 certified filter if the water point is essential and the source of lead is difficult to replace or could not be located and corrected. Retest after corrective work. Inform management, regional public health office, and water supplier.Exceedance in flushed sample may indicate corrosive water or presence of upstream lead plumbing. Investigate other outlets in facility for lead. Expert advice in conducting investigation recommended.
Wickaninnish Community School	24-04-2024	Flushed	CF	Classroom 107	0.0091	Yes	4F	Install a NSF 53/42 certified filter if the water point is essential and the source of lead is difficult to replace or could not be located and corrected. Retest after corrective work. Inform management, regional public health office, and water supplier.Exceedance in flushed sample may indicate corrosive water or presence of upstream lead plumbing. Investigate other outlets in facility for lead. Expert advice in conducting investigation recommended.
Wickaninnish Community School	24-04-2024	First Draw	OT	Staff 139	0.0066	Yes	2A	Post signage near the fixture to run the water at least one minute before drinking or using water for food preparation until replacement. Retest fixture following replacement.
Wickaninnish Community School	24-04-2024	Flushed	OT	Staff 139	0.0005	No	2A	Post signage near the fixture to run the water at least one minute before drinking or using water for food preparation until replacement. Retest fixture following replacement.